

Polaris RZR XP1000 Safety Recall Z-16-01 Identification

Z-16-01-A. *Fuel Tank Vent line replacement.*

Identified by the replacement vent line being black.

The original vent lines were clear



Z-16-01-B. *ECU Recalibration.*


Can only be identified through the Polaris Digital Wrench software

Z-16-01-C. *Voltage Regulator replacement.*

New Regulator is smaller

Old Regulator


New Replacement Regulator



Z-16-01-D. *Heat shield replacement.* Heat indicated by the


red arrow is not present with the original shielding.

The other 3 shields in yellow have been upgraded



Z-16-01-E. *Fuse Box Seal Replacement.*

Old seal is red, replacement new seal is blue



For further information, Please call Lance Whitelock. 0438358217

